

DECON REPORT  
FOR # 115006



REF: WORK INSTRUCTION #7.05.P01.WO17

FIELD SERVICE REPORT (FSR)			
Date/Time: 4/13/20 1300	Unit Area/Shop: ACH	Pos/Loop No.: 3040	Item/Stock No.:
Quantity 1	For: Repair _____ Warranty Repair _____ Replace _____ Evaluate _____ Update _____ Other: _____ (describe below) Other: <u>Sold</u>		
Equipment Description: (Mfg., Model, P/N, Size, Material, etc.) <u>ACH distillation column</u>			
Serial No.:			
Chemical Service History: <u>ACH distillation column</u>			
Safety/Handling Notes: (Sharp Edges, Palletize, Position of Storage, etc.)			
MSDS Attached: <input checked="" type="checkbox"/>	MSDS Not Required: <input type="checkbox"/>	Decontamination Not Required: <input type="checkbox"/>	
Decontaminated by: (print) <u>Joseph Breland</u> Signature <u>J. Breland</u> Clock # <u>161601</u>			
Method of Decon: <u>Triple rinse and N2 purge</u>			
Decontamination was: Completely Successful <input checked="" type="checkbox"/> Possibly incomplete <input type="checkbox"/>			
Follow up Monitoring Data Results: N/A or (Chemical Name & Concentration) <u>N/A</u>			
Follow up Monitoring by: (Print Name & Signature) _____			
Additional Information: (Describe problem, suspected cause of failure, vibration, service conditions, installation date, recommendations, incomplete decontamination, etc., <b>(BE COMPLETE)</b> .)			
<p><b>Note: Field decontamination has been performed in accordance with established procedures for this equipment to current state of disassembly; however, further disassembly of equipment may expose inaccessible cavities containing chemicals. Review MSDS for environmental and personal protective measures.</b></p>			
Authorized Releasing Signature (Production) <u>J. Breland</u>	Printed Name <u>Joseph Breland</u>	Phone Extension: <u>3439</u>	
Authorized Receiving Signature (Maintenance)	Printed Name	Phone Extension:	
If canned motor pump liner has not been removed the following must be completed:	MCE test Performed by:	MCE Results: <u>Attach paperwork</u>	
Comments regarding canned pump shipment:	NDT Test Performed by:	NDT Results: <u>Attach paperwork</u>	