

DECON REPORT
For #115302



REF: WORK INSTRUCTION #7.05.P01.WO17

| FIELD SERVICE REPORT (FSR) | | | |
|---|---|-------------------------------|-----------------|
| Date/Time: 4/13/26 1300 | Unit Area/Shop: ACT | Pos/Loop No.: 3033 | Item/Stock No.: |
| Quantity 1 | For: Repair _____ Warranty Repair _____ Replace _____ Evaluate _____ Update _____ Other: _____ (describe below) Other: Sold | | |
| Equipment Description: (Mfg., Model, P/N, Size, Material, etc.) Shell and tube heat exchanger | | | |
| Serial No.: | | | |
| Chemical Service History: ACT cooler | | | |
| Safety/Handling Notes: (Sharp Edges, Palletize, Position of Storage, etc.) | | | |
| MSDS Attached: ✓ | MSDS Not Required: | Decontamination Not Required: | |
| Decontaminated by: (print) Joseph Breland Signature Jul Bee Clock # 161601 | | | |
| Method of Decon: Triple rinse and N ₂ purge | | | |
| Decontamination was: Completely Successful <input checked="" type="checkbox"/> Possibly incomplete _____ | | | |
| Follow up Monitoring Data Results: N/A or (Chemical Name & Concentration) N/A | | | |
| Follow up Monitoring by: (Print Name & Signature) _____ | | | |
| Additional Information: (Describe problem, suspected cause of failure, vibration, service conditions, installation date, recommendations, incomplete decontamination, etc., (BE COMPLETE). | | | |
| <p>Note: Field decontamination has been performed in accordance with established procedures for this equipment to current state of disassembly; however, further disassembly of equipment may expose inaccessible cavities containing chemicals. Review MSDS for environmental and personal protective measures.</p> | | | |
| Authorized Releasing Signature (Production) | Printed Name Joseph Breland | Phone Extension: 3439 | |
| Authorized Receiving Signature (Maintenance) | Printed Name | Phone Extension: | |
| If canned motor pump liner has not been removed the following must be completed: | MCE test Performed by: | MCE Results: Attach paperwork | |
| Comments regarding canned pump shipment: | NDT Test Performed by: | NDT Results: Attach paperwork | |

STORES 4149580128