


BRUNING 40-103 25302-2



DSS 154
153
193
131
113
114
116
115
114

NOTES

1. COVER ALL FLANGES, OPENINGS AND MACHINED SURFACES PRIOR TO SHIPMENT UNLESS OTHERWISE NOTED.

2. NOZZLE BOLT HOLES SHALL STRADDLE 0-180° CENTERLINE OR ITS PARALLEL UNLESS OTHERWISE NOTED.

~~DSS 153~~ ~~S-24-P~~